ENGINEERING CHANGE NOTICE
DART AEROSPACE LTD

Date: 08.12.05	Job No.: 00569	ADR Yes/No: Y	ADR Date: 08.12.05	ECN #: 08- 575
Product No.: D206-558		Created By:	Approved By:	
Product Name: CARGO MIRROR INSTALLATION		Checked By:	General Manager Approval:	

Distribution	Reqd	Resp	Initial / Date
Production Manager	Y	LL	29.01.14
Production Engineering Coord	Y	EC/DD	09/01/14
Production Document Control	Y	JLD	JO 09.01.14
Customer Technical Support	Y	Dstow	03.01.14

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord	N		
QC Coordinator	N		
Marketing	Y	SW	SW 09.12.14
Customer Order Processing	N		

Reason for Change:
LONGER CABLE REQUIRED FOR INSTALLATION OF CARGO MIRROR ON BHT 407 MODEL AIRCRAFTS

Documents Affected:
RELEASE DSI 9436 REV. A AND D2071 REV. D

PARTS MUST COMPLY ☐   PREVIOUS PARTS SATISFACTORY ☒

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	N			
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N	MB		
5	Update Product Compatability Matrix	Y	Dstow	SEE BELOW.	09.03.11
6	Create Eurocopter Form (FEE)	N			
7	Notify TC / FAA of Change	N			

#	Document Control Actions	Reqd	Resp	Notes	Complete
8	Move Electronic Files	Y	KJ		09.01.14
9	Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ		09.01.14
10	Update Controlled PDF Files	Y	KJ		09.01.14
11	Update Master Document List (MDL)	Y	KJ	696 Rev .D (D2071)	09.01.14
12	Update Document Record (DR)	Y	KJ	558 Rev. I, 696 Rev. D (D2071)	09.01.14
13	Update Product Development Summary	N			
14	Update QSI 021 and/or STC Approval List	N			
15	Update Parts / STC Database	Y	KJ	SEE BELOW.	09.01.14
16	Update / Verify ARC Database	Y	KJ	AS REQUIRED.	09.01.14
17	Create / Update Change Record Form	Y	KJ	AS REQUIRED.	09.01.14
18	Create / Update PPP's	Y	KJ	AS REQUIRED.	09.01.14
19	Update Document Control Database / Laminated Dwgs	N			
20	Update Grey Project Binder	Y	KJ		09.01.14
21	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		09.01.14
22					
23					

Description / Action:
5) DSI 9436-011 KIT IS REQUIRED TO INSTALL D206-558-041/-043 ON BHT 407 MODEL AIRCRAFTS OR USE NEW D407-558-045/-047.
15) CREATE NEW DSI 9436-011 KIT AS WELL AS NEW D407-558-045/-047 KITSAS SHOWN ON PAGE 2 OF DSI 9436..
17/18) DSI 9436-011 @ CHG 001. D407-558-045/-047 @ CHG 001.

DHS WAS NOTIFIED VIA EMAIL OF THE CHANGE. SEE ATTACHED.
ENSURE SALES TEAM UNDERSTANDS THE CHANGES ASSOCIATED WITH THE RELEASE OF DSI 9436 REV A.

ECN Verified & Complete: Date: 09/03/16

Marc Bellavance

From: David Shepherd [dshepherd@dartaero.com]

Sent: January 7, 2009 11:36 AM

To: 'Peggy McDonald'

Cc: mpetsche@dartaero.com; 'Sian Willems'; 'Marc Bellavance'; 'Harvey Siemens'; 'H Mahon'; 'Robbin Fraser'; 'Jennifer Renwick'; 'L Lacelle'; 'Bill Beckett'; 'Holly Menard'; 'Lucie Lamoureux'; 'Dan Stow'

Subject: New 407 Mirror part numbers

Peggy,

As we discussed yesterday, it was discovered during the installation of a D206-558 mirror kit on a 407 here at Eagle that the cable was about 6" too short for the 407. Therefore, we have created new part numbers for the single and dual mirrors that are specific to the 407. The D407-558-045 is the single mirror and the D407-558-047 is the dual mirror. These kits are identical to the -041/-043 kits except for the cable and a thicker grommet. Please see DSI 9436 attached.

Please ensure your sales team is aware of this change and knows to ask whether the mirror is being installed on a 407 or not so that the customer gets the right kit as this change will not be consistent with the information in the 2009 catalogue.

David

No virus found in this outgoing message.
Checked by AVG.
Version: 7.5.552 / Virus Database: 270.10.3/1878 - Release Date: 1/6/2009 7:56 AM